

The Standard

PROPELLER LOC

ASA-SP-

Left



ASA-SP-L

Propeller Record	General Information	•	
	er		
Model			Туре
lub series #		Blade #	
Date of Manufacture .			
			3
	Make/Model		C. C. I.
Aircraft Installed On:	10	Biran	TJ-494 Left Enjine
	,		

/ear:	Total Time in Service	Description		
ate:				
ext Inspection ue:	Time Since Overhaul			
		Mech. Cert. # or Re		
fear:	Total Time in Service	Description	N7243A 58P S/N TJ494 AFTT = Hobbs + 2744.0	
Date:			ENG TT = AFTT -2365.0 or Hobbs $+379.0$	-
Next Inspection Due:	Time Since Overhaul		PROP TT = AFTT -106.3 or Hobbs +2637.7 PROP TSOH = AFTT -2176.0 or Hobbs +568.0	
		Mech. Cert. # or Re	TROI IDOI: 12 1	
Year:	Total Time in Service	Description	1927 N 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Date:			Mr. 1. ad. a	
Next Inspection Due:	Time Since Overhaul			
		Mech. Cert. # or Repa	ir Station #	

/par-	Total Time	Description	HUB & BLADE INSPECTIONS	, REPAIRS A	ND ALTERATION
3 Tom Lar	Malker Aviation mbrecht Drive e IL 60446 506-5327		WindWalker AVIATION SERVICES	REG PROP PROP PROP	PROPELLER :#: N7243A S/N: 850141 TSOH: 568.0 PTT: 2637.7
I certify to Regulation the work Signed:	ns, and has been performed. Per	inspection of the LH p engine, propeller or c n determined to be air tinent details are on fil	propeller per CFR43 Appendix D. No dis component has been maintained as required tworthy condition and approved for returnile at this repair station with the named w 07/02 meoville, IL 60446, FAA Certificated Repair Station No	red by the Fe n to service i vork order.	noted. ederal Aviation with respect to WO#: 1174
C.	Overnaui		Station No	.W4LR644Y	

$\ \square$ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

	Emery Air, Inc.	14 Oct, 2008
BE 58P	Hawker Beechcraft Service Center	WO: PT-60018
N7243A	Greater Rockford Airport-Rockford, IL 61109	HM: 45.4
TJ-494	FAA Approved Repair Station No. E81R759X/EASA.145.4811	PTSN:
3AF320511-B	Left Propeller	TSO:
s/n: 850141	Lett Topcher	

Removed propeller from left position of N7243A for maintenance.

Signed: LEMERY AIR INC.

Greater Rockford Airport, Rockford, IL 61109

F.A.A. Approved Repair Station No. E81R759X/EASA.145.4811

lext Inspection	Time Since Overhaul		
ue:	Overhaul		
		Mech. Cert. # or Repair Station #	

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS $\ \Box$

Total Time Description

BE 58P	Emery Air, Inc.	·
N7243A		26 Nov, 2008
	Hawker Beechcraft Service Center	WO: PT-60018
TJ-494	Greater Rockford Airport-Rockford, IL 61109	
3AF320511-B	FAA Approved Repair Station No. E81R759X/EASA.145.4811	ACTT: 2789.4
s/n: 850141		HM: 45.4
5/11. 050 [4]	Left Propeller Log Insert	ETSN: 424.4

Reinstalled propeller after repair by Aircraft Propeller, CRS# EY2R811K. See 8130-3 tracking no 26977C for details. Ground run and operational check good. MM 61-10.

MAINTENANCE RELEASE

WO: PT-60018

Date: 10-26-08

Approved for Return to Service With Respect to the Work Performed EMERY AIR INC.
Greater Rockford Airport, Rockford, IL 61109
F.A.A. Approved Repair Station No. E81R759X/EASA.145.4811

Hawker Beechcraft Services, Inc. IND 6821 Pierson Drive Indianapolis, IN 46241 Ph. (317)240-5077 fax (317)240-5092

LEFT PROP LOG ENTRY

MODEL 3AF32C511-B A/C S/N TJ-494 A/C REG. N7243A

WORK AC TT ORDER# 03-04-2354 2836.9 hrs

AC TCYC:

HR MTR:

DATE

LT Prop TT

92.9 hrs

8-13-09

LT Prop SN 850141

2730.6 hrs

LT Prop CSN

LT Prop TSO

660.9 hrs

Annual / 100 Hour Inspection, IAW Baron Annual or 100 Hour Long Form Inspection Guide. 100 Hour Electric Propeller De-ice Inspection.

Performed ground runs. Leak checks and ground operational checks in accordance with the inspection guide. I certify that this Propeller has been inspected in accordance with the instructions and procedures of a current manufacturer's recommended inspection program, approved for 14 CFR Part 91.409(a)(1) and was determined to be in airworthy condition.

Hawker Beechcraft Services CRS-ML2R009L EASA 145.6120

Name: David W. Pieper

Title: Inspector

	ROP MODEL (L): F32C511-B	Gryphon Aircraft Services, LLC.	DATE 10/000010 A/C TSN: 3061.9	.TERATIONS
Year:	Total OP S/N (L): 850141 in SeEG, NO: N7243A ORK ORDER: urrieta3526 08-2010	Repair Station No, CRS 2SDR271B 37880 Sky Canyon Drive Murrieta, CA 92563 Phone: 951-775-1932	PROP TT (L): 3061.9 TSPOH (L): 885.9 HOBBS: 317.9	1
pare.	eft Prop Entries			
Next Inspection Due:		spection per manufacturer's and Gryphon Aircraft Services	Inspection forms	The standard and
fear:	condition. All work pe	PELLER has been inspected IAW and ANNUAL inspection formed IAW applicable service manuals or other approved air facility under Work Order No. Murrieta3526-08-2010. FA	documentation. Pertinent details of the repair	
ate:				
Next Inspection Due:	PROP MODEL (L): 3AF32C511-B Tim PROP SN (L): 850141 Ove REG. NO: N7243A WORK ORDER: Murrieta3615-11-2010 Left Prop Entries	Gryphon Aircraft Services, LLC. Repair Station No. CRS 2SDR271B 37680 Sky Canyon Drive Murrieta, CA 92563 Phone: 951-775-1932	DATE: 12/8/2010 A/C TSN: 3078.5 PROP TT (L): 3078.5 TSPOH (L): 902.5 HOBBS: 334.5	20 10 10 10 10 10
	Tot R&R L/H prop for re-si	eal Santa Monica Propeller Service CRS ZY2R362L		
ear:	in !	ear Santa Monica Propeller Service CRS ZY2R362L		
ate:	The above identified A regulations and is APF	ircraft, Engine, Propeller or Appliance was repaired and insp PROVED for return to service. All work performed IAW applicant ent details of the repair are on file at this repair facility under	pected in accordance with current FAA	740
ext Inspection ue:	documentation. Pertine FAA CRS #2SDR271E Ov DATE: 12/8/2010	ent details of the repair are as full and	work Order: Murrieta3615-11-2010	
			Printed by EBis 3 (datcomedia.com)	

LEST PROP 3. Form Tracking Number: 1. Approving National Aviation AUTHORIZED RELEASE CERTIFICATE Yε Authority/Country: 11-34165 FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG FAA/United States Da 5. Work Order/Contract/Invoice 4. Organization Name and Address: Byam Propeller Serv. Inc. 4001 N. Main Hanger 7 South Ft. Worth, Texas 76106 (fax) 817-626-0009 Ne (tel) 817-625-0161 Number: 34165 (tel) 817-625-0006 Dı Status/Work: Serial/Batch Number: 12. 10. Quantity: 11. 9. Eligibility: * Part Number: Description: 6. Item: = McCauley service 850141 3AF32C511-B n/a Propeller Ye 13. Remarks: Di Profile and polane paint and balance. Install boots. I/A/W Manual MPC500. ----end----N Di Other regulatiospecified in Block 13 10 W 14 CER 43 9 Return to Service **Next Inspection Time Since** Overhaul Mech. Cert. # or Repair Station # -

Dallas Executive Aircraft Service, LLC Phone: 214-558-1238 Email: shavermchad@gmail.com	Aircraft: N7243A S/N: TJ-494 Left Propeller Log	Model: 3AF32C511-B S/N: 850141	ERATIO
obs: 553.0 TSMOH: 1121.0 rtify that this propeller has been inspected in accordition. 5/23/14 Chad Shaver A&P 2857120	ance with a 100Hr Inspection	and was determined to be in airworthy	
Dallas Executive Aircraft Service, LLC Phone: 214-558-1238 Email: shavermchad@gmail.com	Aircraft: N7243A S/N: TJ-494 Left Propeller Log	Model: 3AF32C511-B S/N: 850141	

HUB & BL	ADE INSPEC	TIONS, REPAIRS AND ALTERATIONS Plocking and this aircraft engine has been
Year: 2017	Total Time in Service	Description d in accordance with an annual
Date: OG MA		Note: A 100 hr inspection and was determined to be in an airworthy condition.
Next Inspection Due:	Time Since Overhaul	Mech. Cert. for Repair Station # AP3040415IA
Year:	Total Time in Service	Description CERTIFICATE NO.
Next Inspection Due:	Time Since Overhaul	
	200	Mech. Cert. # or Repair Station #
Year:	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station #

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS \Box



BROADIE'S AIRCRAFT

Meacham International Airport

4701 N. Main St., Loc 44N, Fort Worth, Texas 76106

TJ-494

850141

817-626-1532

www.BroadiesAircraft.com

Aircraft Registration #

N7243A

S/N:

PTT 3139.4 **TSMOH** 1263.4

McCauley Description of work performed:

Model: 3AF32C511

S/N:

Propeller 1

HOBBS 695.4

C/W Beechcraft 58P Annual Inspection. IAW 5-20-00

I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. All work was done IAW the manufacturers service instructions and the aircraft is approved for return to service in regards to the work performed.

Signature:

Repair Station # WF1R582K

Date: 4/19/2018





Repair Order # 18-002282

Next Inspection

Time Since Overhaul

Mech. Cert. # or Repair Station #

AIRW		- I - A B	21
Year:		AIRCRAFT MECHANICAL SE	
		9519 Airport Drive, Ha	
Date:		Visalia, CA 9327	
A.D. #		<u>Left Propelle</u>	
	DATE: 7/1/19	MODEL:	HOBBS: 811.0
	REG: N7243A	S/N:	
	ANNUAL INS	PECTION COMPLETED THIS DATE. ALL APP	PLICABLE AD'S CHECKED AND C/W
Next Inspe	OR N/A AS LISTED IN AD LOG. I CERTIFY THAT THIS PROPELLER WAS INSPECTED IN ACCORDANCE		
	WITH ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.		
		FOR RETURN TO SERVICE.	
	APPROVED	FOR RETURN TO SERVICE.	
Year:			
Date:			STEPHEN STEWART - IA 2129169
Date:	PERTINENT	DETAILS ON FILE: W.O. 724070119	
A.D. #			
		-	
Next Inspect Due:	ion		
Duc.			
	Mech. Cert. # o	r Repair Station #	