

OWNER'S MANUAL PROPELER B



HVD12EII DDODLI'LD II'O

HARTZELL PROPELLER INC INSPECTION 1507170B_2R Item Number: F3R00060 Work Order #: M638860 Date: 10/9/2012


RIGHT


Position)

Comments: Deice Kit: 77-045-1	Ass'y Ser No. DA1778B Blade 1:L29437 Clamp 1: Reverse NA NA Ref Radius (inches) for angles: 30	Model Number HC-F3YR-2UF/FC7479B-2R
Included but not inst.	Bulkhead No. NA Blade 3:L294 Clamp 3: Ch Feather 81.7	R-2UF/FC7479B-2R
	A40 Bla Cla	Valve No.

Inspected By: John Martin Packing Certified By: The approved design data for this propeller incoporates all changes required by applicable Airworthiness Directives. Date an oranges required by applicable Airworthiness Directives

Deice Kit: 77-045-1





Date

Propeller TSN TSO

Hrs C

Description of all operations Service Documents, Overhau



MAINTENANCE SERVICE


145 S. GENE AUTRY TRAIL

N41ST 01-15-2015 Hobbs: 1248.0 TTP: 128.3

condition. This prop is approved for returned to service....... detail of FAR 43 appendix D and was determined to be in airworthy been inspected I/A/W a 100 hr / annual inspection within the scope & Right Prop.. Serviced hub with lube & Nitrogen. I certify this prop has

Robert Scott

A&P 2719327



							Date	
							Propeller TSN TSO	
	Bu	I certify that this return to service T Brown 293262	M/n;	Hartze Propel N41ST	200 Skyli Reg. N41ST Date:07-24-19		A/C Hrs	
	w	I certify that this PROPELLER has been inspected and repaired and is ok for return to service. T Brown 2932628 A/P	M/n; HC-F3YR-2UF, s/n;DA1778B	Hartzell propeller removed. Sent to Sullivan Propeller Service for flush/repair. Reinstalled onto N41ST per Hartzell and Beechcraft M/M.	200 Skylane Dr. Hollister, Ca 95023 (831)637-9100 V41ST Hobbs:1265.3 Propeller Log 07-24-19 Tsoh: Prop. TT: M5, O	Hollister Jet Center	Description of all operations pertaining to Air Service Documents, Overhaul, Major or Minor Re-	

FRVIC

PROPELLER

Unit Name

HARTZELL

Manufacturer

HC-F3YR-2UF

DA1778B

Mode

Serial

repaired/overhauled and inspected in accordance with the The propeller or appliance identified above was

117D

overhaul manual and current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this repair station under:

HOLLISTER JET CENTER

Owner Name

113

11/16/2018

< 10

Work Order Number

Date

Nicolas H. Penate



SULLIVAN PROPELLER SPECIALISTS 2156 American Avenue Hayward, CA 94545 tel: 510.782.0920

fax: 510.264.9162

FAA Repair Station No. S5UR963J www.sullivanpropeller.com

SPS-106 (front)

and AD listing. and determined to be in airworthy condition at this time. Complied with Inspection checklist as per Appendix D to Part 43. For AD compliance, see recurring AD sheets I certify that this **Propeller** has been inspected in accordance with a **Annual Inspection**

Hobbs

TTProp | 145.0

Flight Sport Aviation, LLC Anthony Bell A&P, IA



Authorized Signature



Reg. No. - N41ST RT Prop Hartzell HC-F3YR-2UF S/N DA1778B

and AD listing checklist as per Appendix D to Part 43. For AD compliance, see recurring AD sheets and determined to be in airworthy condition at this time. Complied with Inspection I certify that this Propeller has been inspected in accordance with a Annual Inspection

Date -

Hobbs TTProp | 149.0 1269.3

Flight Sport Aviation, LLC Anthony Bell A&P, IA



Authorized Signature

A&P2145613IA