


PROPELLER MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION T18208761 N1827MC

PROPELLER MODEL AND SERIAL B3D36C 442 / 80V4B-1

HUB SERIAL 070970 071362 BLADE SERIALS ABE26004, ABE26008, ABE26010
ABH26032 ABH26040 ABH26041

MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
2007 09/14	7	0	Propeller hub S/N <u>070740</u> , blade S/N #1 <u>ABE26004</u> , S/N #2 <u>ABE26008</u> and S/N #3 <u>ABE26010</u> has been installed on engine S/N <u>L-12768-61A</u> on aircraft <u>T18208761</u> . With TTAFF <u>7.0</u> TTSN was <u>7.0</u> .	 ODARF100129CE

HETRICK AIR SERVICES, Inc. 1930 Airport Road
Lawrence, Ks. 66044
Phone: (785) 842-0000

Propeller Log
N182MC
Cessna T182T
S/N T18208761

McCauley
B3D36C442
SN 071362

December 21, 2007 Tach Time: 24.2 Hrs. Total Time: 0.0 Hrs Work Order # 07- 5528
Removed old propeller (S/N 070740) and replaced with new one (P/N B3D36C442, S/N 071362). Installed with new o-ring (P/N A1633-11). Details pertinent to this repair are on file under work order #07-5528.

Hetrick Air Services, Inc.
FAA Approved Repair Station #VKDR861X

Lloyd A. Hetrick 2859510

MAINTENANCE RECORD

DATE 19__	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
04/26/08	TACH	93.7	C.W. Propeller Annual/100hr inspection. Found Propeller to be in Airworthy condition.	<i>Matthew A. Pikes</i> PVC R320H
	PTT	69.5		
10/03/08	Tach	296.2	CW Propeller Annual/100hr inspection. Determined prop to be in Airworthy condition	<i>Matthew A. Pikes</i> PVC R320H
	PTT	172.0		
PAVCO FLIGHT CENTER FAACRS PVC R320H N# <u>182MC</u> MFG <u>McCauley</u> MODEL <u>B3D36C442</u> Tacoma Narrows Airport S/N <u>070740</u> W.O.# <u>02875</u> DATE <u>11/01/2009</u> 1110 26 th Ave N.W. Gig Harbor, WA 98335 TACH: <u>372.1</u> ACTT <u>372.1</u> Prop.TT <u>296.5</u>				
C.W. Propeller 100hr/ANNUAL inspection, dressed propeller blades. Determined prop to be in AIRWORTHY condition. <i>Matthew A. Pikes</i> PVC R320H				

Northwest Propeller Service, Inc.
 16607 103rd Ave. Ct. E.
 Puyallup, WA 98374

REPAIR STATION No. IT6R625N

W/O 23607 Mfg: McCauley Model: B3D36C442 s/n: 071362
 Repaired, profiled and painted blades. Removed and replaced cylinder. Pressure tested, balanced and lubed propeller per McCauley manuals MPC400-Rev. 2, SPM400-04 Rev.4 and BOM100-04 Rev. 4.

Ken Shales
 Inspector
 Cert. No. 2647558

December 14 2010
 Date

DATE 19__	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10th		
			Removed propeller for repair by N.W. Propeller Service and reinstalled after C.W. Propeller 100hr/ANNUAL inspection, dressed propeller blades. Determined prop to be in AIRWORTHY condition.	<i>Matthew A. Pikes</i> PVC R320H
PAVCO FLIGHT CENTER FAACRS PVC R320H N# <u>182MC</u> MFG <u>McCauley</u> MODEL <u>B3D36C442</u> Tacoma Narrows Airport S/N <u>070740</u> W.O.# <u>03083</u> DATE <u>12/15/2010</u> 1110 26 th Ave N.W. Gig Harbor, WA 98335 TACH: <u>594.8</u> ACTT <u>594.8</u> Prop.TT <u>519.2</u>				

MAINTENANCE RECORD

DATE 19__	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
			PAVCO FLIGHT CENTER FAACRS PVCR320H N# <u>182MC</u> Tacoma Narrows Airport S/N <u>070740</u> 1110 26 th Ave N.W. Gig Harbor, WA 98335 TACH: <u>741.7</u>	MFG <u>McCauley</u> MODEL <u>B3D36C442</u> W.O.# <u>03283</u> DATE <u>12/09/2011</u> ACTT <u>741.7</u> Prop.TT <u>741.7</u>

Inspected propeller, dressed propeller blades. I certify this propeller has been inspected in accordance with an ANNUAL inspection and was determined to be in AIRWORTHY condition..

Muttan A Midway PVCR320H

Jewell Aviation Inc.

418 Airport Rd.
P.O. Box 623
Kennett, MO 63857
573-888-5846
www.jewellaviation.com

Make:	McCauley
Model:	B3D36C442/80VSB-1
Serial#	070740 071362
Date:	12/7/2012
Hobbs Time:	882.3
Tach <i>TA</i> :	806.8
N182MC	

TA3036572

This date performed an annual inspection, removed all nicks and painted back of blades flat black. I have inspected and determined this propeller to be in airworthy condition.

David Jewell IA3036572

MAINTENANCE RECORD

DATE 19__	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10ths		
			Jewell Aviation Inc. 418 Airport Rd. P.O. Box 623 Kennett, MO 63857 573-888-5846 www.jewellaviation.com	Make: McCauley Model: B3D36C442/80VSB-1 Serial# 071362 Date: 1/29/2014 Hobbs Time: 916.2 Tach Time: 831.6 Total Time: 807
			This date performed an annual inspection, removed all nicks and painted back of blades flat black. I have inspected and determined this propeller to be in airworthy condition.	<i>David Jewell IA3036572</i>

MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		<p>PROP MODEL: PROP S/N: REG. NO: N182MC WORK ORDER: 26506</p> <p>APR Aviation, Inc. Repair Station No. CP3R431L 5041 E. Andersen Ave Fresno, California 93727 USA Phone: 800-982-8466</p>	<p>DATE: 3/16/2015 A/C TSN: 912.7 PROP TT: 912.7 TACH: 912.7</p>	<p style="text-align: center;">AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER</p>
	HOURS	10ths			
19__			<p>Prop Entries (3) Complied with 100hr inspection I/A/W APR Aviation Checklist.</p> <hr/> <p>I certify that the propeller identified above has been inspected in accordance with a 100 hour inspection and has been found airworthy as of this date.</p> <p>DATE: 3/16/2015 SIGNED: Work Order: 26506</p> <p style="text-align: center;">Robert Lawrence Printed by EBis 3 (datcomedia.com) Certified Repair Station No. CP3R431L</p>		

MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		<p>PROP MODEL: B3D36C442 PROP S/N: 071362 REG. NO: N182MC WORK ORDER: 27927</p> <p>APR Aviation, Inc. Repair Station No. CP3R431L 5041 E. Andersen Ave Fresno, California 93727 USA Phone: 800-982-8466</p>	<p>DATE: 4/6/2016 A/C TSN: 961.6 PROP TT: 937.4 TACH: 961.6</p>	<p style="text-align: center;">AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER</p>
	HOURS	10ths			
19__			<p>Prop Entries (3) C/W 100Hr Propeller Inspection.</p> <hr/> <p>I certify that the propeller identified above has been inspected in accordance with a 100 hour inspection and has been found airworthy as of this date.</p> <p>DATE: 4/6/2016 SIGNED: Work Order: 27927</p> <p style="text-align: center;">Joseph Woolsey Printed by EBis 3 (datcomedia.com) Certified Repair Station No. CP3R431L</p>		

DATE	TOTAL TIME IN SERVICE	
	HOURS	10ths
19__		

PROP MODEL:
B3D36C442
PROP S/N: 071362
REG. NO: N182MC
WORK ORDER: 29164



APR Aviation, Inc.
Repair Station No. CP3R431L
5041 E. Andersen Ave
Fresno, California 93727 USA
Phone: 800-982-8466

DATE: 6/1/2017
A/C TSN: 996.1
PROP TT: 971.9
TACH: 996.1

Prop Entries

(3) C/W 100hr inspection I/A/W FAR 43 appendix D utilizing APR Aviation Checklist.

I certify that the propeller identified above has been inspected in accordance with a 100 hour inspection and has been found airworthy as of this date.

DATE: 6/1/2017

SIGNED:

[Signature]
Joseph Woolsey
Certified Repair Station No. CP3R431L

Work Order: 29164

Printed by EBis 3 (datcomedia.com)

**AUTHORIZED SIGNATURE
CERTIFICATE TYPE
& NUMBER**

PROP MODEL:
B3D36C442
PROP S/N: 071362
REG. NO: N182MC
WORK ORDER: 30487



APR Aviation, Inc.
Repair Station No. CP3R431L
5041 E. Andersen Ave
Fresno, California 93727 USA
Phone: 800-982-8466

DATE: 7/16/2018
A/C TSN: 1025.6
PROP TT: 1001.4
TACH: 1025.6

Prop Entries

(3) C/W 100hr/Annual inspection I/A/W FAR 43 appendix D utilizing APR Aviation Checklist.----(17)
Removed one prop deice boot. Installed new de-ice boot. Operational check good.

I certify that the propeller identified above has been inspected in accordance with a 100 hour/Annual inspection and has been found airworthy as of this date.

DATE: 7/16/2018

SIGNED:

[Signature]
Stephen Denney
Certified Repair Station No. CP3R431L

Work Order: 30487

Printed by EBis 3 (datcomedia.com)

S.B. NUMBER	DATE OF COMPLIANCE

PROP MODEL:
B3D36C442
PROP S/N: 071362
REG. NO: N182MC
WORK ORDER: 31644



APR Aviation, Inc.
Repair Station No. CP3R431L
5041 E. Andersen Ave
Fresno, California 93727 USA
Phone: 800-982-8466

DATE: 8/21/2019
A/C TSN: 1031.4
PROP TT: 1007.2
TACH: 1031.4

Prop Entries

(3) C/W 100hr/Annual inspection I/A/W FAR 43 appendix D utilizing APR Aviation Checklist.

I certify that the propeller identified above has been inspected in accordance with a 100 hour/Annual inspection and has been found airworthy as of this date.

DATE: 8/21/2019

SIGNED:

[Signature]
Stephen Denney
Certified Repair Station No. CP3R431L

Work Order: 31644

Printed by EBis 3 (datcomedia.com)

RE.	REMARKS

PROP MODEL:
B3D36C442
PROP S/N: 071362
REG. NO: N182MC
WORK ORDER: 32395



APR Aviation
Repair Station No. CP3R431L
5041 E. Andersen Ave
Fresno, California 93727 USA
Phone: 800-982-8466

DATE: 8/21/2020
A/C TSN: 1035.8
PROP TT: 1011.6
TACH: 1035.8

Prop Entries

(3) C/W 100hr/Annual inspection I/A/W FAR 43 appendix D utilizing APR Aviation Checklist.

I certify that the propeller identified above has been inspected in accordance with a 100 hour/Annual inspection and has been found airworthy as of this date.

DATE: 8/21/2020

SIGNED:

[Signature]
Stephen Denney
Certified Repair Station No. CP3R431L

Work Order: 32395

Printed by EBis 3 (datcomedia.com)