### REMARKS

### **SIGNATURE**



9519 Airport Drive, Hanger 19 Visalia, CA 93277

# <u>Airframe</u>

DATE: 06/11/18 MODEL: PA-18-150

ACTT: 3442.0

TACH: 3442.0

REG: N4230Z S/N: 18-8456

1 REMOVE & REPLACE AIRCRAFT BATTERY P/N:G-35 S/N:G02998446 & SERVICE WITH 3 QTS OF ACID.

2 REPLACE ELT BATTERY P/N:BS2166.

3 INSPECTED ELT IN ACCORDANCE WITH FAR 91.207(D). (DUE JUNE 2020).

STEPHEN STEWART - A&P 2129169

ALECKA OF LOS	N C

	ate	Time in A Hrs.	ir Min.	Passengers Carried	NATURE OF FLIGHT
Year Mo.	Day	W. S. C.		B. A.	
				4	



9519 Airport Drive, Hanger 19 Visalia, CA 93277

# **Airframe**

DATE: 6/24/19

**MODEL: PA-18-150** 

**ACTT: 3445.0** 

**TACH: 3445.0** 

**REG: N4230Z** 

S/N: 18-8456

1 INSTALL NEW AIR FILTER PN:2220.

2 INSPECTED ELT IN ACCORDANCE WITH FAR 91.207(D) (DUE 6/20).

STEPHEN STEWART - A&P 2129169

### PERTINENT DETAILS ON FILE: W.O. 423062419

			212	
Total F	orward		1	

Place of Last Airplane Overhaul .....

Date of Last Overhaul.....

NOTICE: -- Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

### REMARKS

### **SIGNATURE**



9519 Airport Drive, Hanger 19 Visalia, CA 93277

# **Airframe**

DATE: 6/24/19

**MODEL: PA-18-150** 

**ACTT: 3445.0** 

**TACH: 3445.0** 

**REG: N4230Z** 

S/N: 18-8456

ANNUAL INSPECTION COMPLETED THIS DATE. ALL APPLICABLE AD'S CHECKED AND CAVOR N/A AS LISTED IN AD LOG. I CERTIFY THAT THIS AIRFRAME WAS INSPECTED IN ACCORDANCE WITH <u>ANNUAL</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

APPROVED FOR RETURN TO SERVICE.

STEPHEN STEWART - IA 2129169

Date	Time in Air Hrs.	Passengers		NATURE OF FLI	СНТ	Minute pro
ear	Hrs. N	din. Carried		NATURE OF FLI	uni.	
Mo. Day						
Martine series	Park Addition to the Park			and the second s	Alleren werd in Malerian America. Consider Americans St. 1997	rises i editorio e
1						
and the second s	the set of A subspiced registers of subspices of the set of the se	All	CRAFT MECHANICAL SER	VICES, Inc.	et i destri metata meneripti terditterio i i cada presenzata nasi sonita es	phonic declaration of the services
special and the second second	der, erfemme get ner ellekterternen der in år i som	ministra i gual promittaga ero	9519 Airport Drive, Han		getrok dig is hir, iris, responsense samme deletrorise dy . J. N. is the cystes, consignite by a clar	etholic sepapatat a tro
marin for	and the second contract of the second	Carrier destroy	Visalia, CA 93277	The property of the second problem of the second seconds of the second s	and are a section to the section of	ricis, is estingated time
		form approximately the contract	<u>Airframe</u>		ngi 1-6, semigiren, many indistry ya dismini ilimini pinkapianaki shika dismini pakabanaki, ma	a ex Milyandov
DATE: 10/16	/19 MOI	DEL: PA-18-150		ACTT: 3446.02	TACH: 3446.02	
<b>REG: N42302</b>	Z S/N:	: 18-8456			The second secon	The same filtragement
1 INSTALL	NEW DIAPH	RAGMS P/N: 284	4 ON LEFT & RIGHT	MASTER CYLINDEI	RS FOR BRAKES.	tic superhalage spiral i N
an experience of the same of the	a policy and reduced and area	a thurse to right yell system to prove the system is not specified.	A construction or while the Supersylving product over a structure	a. Danisti neri tahung sa silikupunanna pahinyi is ilipatitiyonyi nyi ii qost isinaliy	acupulman i Bancohaganin on ilikab tapak i lah wilisan tapaksalah sa k	profess was professorial
	of a market seconds of fragility	and the second s	The security of the second security and the second	the transfer was a section with a consequence of	1/1/1	erites, temperantifica
a tipote interpretation of code on some	eter and a stanting of the second second	na a pamie nel e communicación e e e esc		ENTRAL TORS OF THE SALE OF THE	AEL LODEZ ARD 2	70070
			100101010	KAPII	AEL LOPEZ - A&P 2	./05/0
PERTINI	ENT DETAILS	ON FILE: W.O.	423101619	- Anna - Anna againean - Anna anna anna anna anna anna anna	ille – in Anthrichenskin Streegerich usträttigt in Anthrichensen meiser steffic Anthriphilabilitätete (s. 1600 – 1600)	TOPP - SUMBLE CON
		:		let a	THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAM	
<del>-   -  </del>	<del></del>				# 94 54 5 TEAR	
					The state of the s	
Total Forward	•		e e			
Place of Le	st Airnlane	Overhaul			AND AND SOUTH OF THE PARTY OF T	
Date of Las	st Overhaul.				•••••	
NOTICE: -M	aking false enti	ries in this book is	a violation of the Civil	Aeronautics Act of 1938	, punishable by Civil Pe	

#### **REMARKS**

#### **SIGNATURE**



9519 Airport Drive, Hanger 19 Visalia, CA 93277

### <u>Airframe</u>

DATE: 08/12/20

MODEL: PA-18-150

**ACTT: 3447.25** 

**TACH: 3447.25** 

**REG: N4230Z** 

S/N: 18-8456

ANNUAL INSPECTION COMPLETED THIS DATE. ALL APPLICABLE AD'S CHECKED AND CAVOR NA AS LISTED IN AD LOG. I CERTIFY THAT THIS AIRFRAME WAS INSPECTED IN ACCORDANCE WITH <u>ANNUAL</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

APPROVED FOR RETURN TO SERVICE.

STEPHEN STEWART - IA 2129169

Date	Time in Air Hrs. Mi	Passengers in. Carried	NATURE OF	FLIGHT
Mo REPLACE ELT BATTERY BY:				
	MAR 2022			
_	WALL TO			
	-			
			Drive, Hanger 19	
	-		a, CA 93277	
		<u>Air</u>	<u>frame</u>	
ATE: 08/12	/20 MODEL	.: PA-18-150	ACTT: 3447.25	TACH: 3447.25
EG: N4230	Z S/N: 18	-8456		
1 REMOV	E & REPLACE EL	T BATTERY P/N: BS2166	& TESTED.	
2 INSPEC	TED ELT IN ACC	ORDANCE WITH FAR 91	.207(D) (DUE 6/22).	1/-/
-				X Par
			CHRIST	AN MUNOZ - A&P 35594
PERTIN	ENT DETAILS ON	FILE: W.O. 423081220		
1 517111				
otal Forward		s 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		No. 10 Table State Control of the

NOTICE: -Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

	AIRCRART I.	AL 1
MAKE: Piper MODEL: PA18-150 S/N: 18-8456 REG. NO: N4236Z WORK ORDER: 4609-10-2020	Valley Air Crafts. P.O. BOX 566 Tulare, California 93275 Phone: 559-686-7401	DATE: 11/2/2020 A/C TSN: 3447 TACH: 3447
Airframe Entries		
(1) Repaired several sm manual (2) Bled the ri	nall fabric tears on the fuselage using Stits Poly-Fiber ight and left brake systems (3) Installed a metal ins	materials and the Stits Poly-Fiber process spection plate cover on the bottom of the fuseiage.
DATE: 11/2/2020	SIGNED:	Work Order: 4609-10-2020
	Michael Schoenau, A&P: 3262337	Printed by EBis 3 (datcomedia.com)
		· —
		-
		_

Date	Time Hrs.	in Air Min.	Passengers Carried	NATURE OF F		
Mo, Day			TO THE STATE OF TH			
	9519 Airpo			MECHANICAL SERVICES, inc. Airport Drive, Hanger 19		
				Visalia, CA 93277  Airframe		
DATE: 03/0	3/22	MODEL:	PA-18-150	ACTT: 3449.90	TACH: 3449.90	
REG: N4230	7	C/N: 40 0	450			
REG. N4230	2	S/N: 18-84	450			
				Y P/N: G-35 S/N: G0314868 & SER\	/ICED WITH 3 QUARTS	
1 REMOV		LACE AIRC		Y P/N: G-35 S/N: G0314868 & SER\		
1 REMOV	E & REP	LACE AIRC				
1 REMOV	E & REP	LACE AIRC			2/13	
1 REMOV OF BAT	E & REP	LACE AIRC	CRAFT BATTERY	RAPH		
1 REMOV OF BAT	E & REP	LACE AIRC		RAPH	2/13	
1 REMOV OF BAT	E & REP	LACE AIRC	CRAFT BATTERY	RAPH	2/13	
1 REMOV OF BAT	E & REP	LACE AIRC	CRAFT BATTERY	RAPH	2/13	
1 REMOV OF BAT	E & REP	LACE AIRC	CRAFT BATTERY	RAPH	2/13	
1 REMOV OF BAT	E & REP	LACE AIRC	CRAFT BATTERY	RAPH	2/13	

NOTICE: -Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

MAKE: Piper MODEL: PA18-150 S/N: 18-8456 REG. NO: N4230Z WORK ORDER: 4866-05-2022	Valley Air Crafts.  P.O. BOX 566 Tulare, California 93275 Phone: 559-686-7401	DATE: 5/13/2022 A/C TSN: 3450 TACH: 3450
Airframe Entries	a cords on the landing goes check start units	
(1) Installed new bunge	e cords on the landing gear shock strut units.	
DATE: 5/13/2022	SIGNED:	Work Order: 4866-05-2022
.>	Michael Schoenau, A&P: 3262337	Printed by EBis 3 (datcomedia.com)

Date

Time in Air Hrs. Min. Passengers Carried

NATURE OF FLIGHT



9519 Airport Drive, Hanger 19 Visalia, CA 93277

#### **Airframe**

DATE: 05/18/22

**MODEL: PA-18-150** 

ACTT: 3450.2

TACH: 3450.02

**REG: N4230Z** 

S/N: 18-8456

- 1 C/W AD 68-05-01 R1 BY INSPECTION OF EXHAUST MUFFLERS.
- 2 REMOVE & REPLACE ENGINE MOUNT BUSHINGS P/N: 71032.
- 3 REPLACED O-RING P/N: MS29513-011 ON FUEL SELECTOR VALVE.
- 4 REMOVE & RE-INSTALL L/H & R/H GEAR STRUTS FOR VALLEY AIRCRAFTS TO REPLACE BUNGEE CORDS P/N: 06-00826, INSTALLED WITH NEW BOLT'S P/N: AN6-17.
- 5 RESEALED BREAK CALIPERS BY REPLACEMENT OF O-RING P/N: MS28775-222.
- 6 REMOVE & REPLACE ELT BATTERY P/N: BP-1010 (EXP. 05/2024) & TESTED.
- 7 INSPECTED ELT IN ACCORDANCE WITH FAR 91.207(D) (DUE 5/24).

RAPHAEL LOPEZ - A&P 2709706

PERTINENT DETAILS ON FILE: W.O. 423051822

Date of Last Overhaul.

#### REMARKS

SIGNATURE



9519 Airport Drive, Hanger 19 Visalia, CA 93277

#### **Airframe**

DATE: 05/18/22

MODEL: PA-18-150

ACTT: 3450.2

TACH: 3450.02

REG: N4230Z

S/N: 18-8456

ANNUAL INSPECTION COMPLETED THIS DATE. ALL APPLICABLE AD'S CHECKED AND CAW
OR N/A AS LISTED IN AD LOG. I CERTIFY THAT THIS AIRFRAME WAS INSPECTED IN ACCORDANCE
WITH <u>ANNUAL</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

APPROVED FOR RETURN TO SERVICE.

STEPHEN STEWART - IA 2129169

T	C
. 7	·····



9519 Airport Drive, Hanger 19 Visalia, CA 93277

# **Airframe**

DATE: 11/30/22

**MODEL: PA-18-150** 

**ACTT: 3451.85** 

TACH: 3451.85

**REG: N4230Z** 

S/N: 18-8456

1 REMOVE & REPLACE TAIL WHEEL ASSY HARDWARE BOLT P/N: AN7-21A, WASHERS

P/N: 80122-030 & 85012-048, BUSHING P/N: 751-350 & SPACER P/N: 752-888.

RAPHAEL LOPEZ - A&P 2709706

PERTINENT DETAILS ON FILE: W.O. 423113022

	1		
			THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.
		ŀ	
		î.	and the second s
		1	e e e e e e e e e e e e e e e e e e e
Total Forward			

Place of Last Airplane Overhaul .....

Date of Last Overhaul.....

NOTICE: -- Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.

# REMARKS

#### SIGNATURE



9519 Airport Drive, Hanger 19 Visalia, CA 93277

### **Airframe**

DATE: 04/24/23

**MODEL: PA-18-150** 

**ACTT: 3455.0** 

TACH: 3455.0

**REG: N4230Z** 

S/N: 18-8456

- 1 REMOVE & REPLACE MAIN AIRCRAFT BATTERY P/N: RG-25XC.
- 2 REMOVE & REPLACE TERMINAL ASSY P/N: 112440.
- 3 INSPECTED ELT IN ACCORDANCE WITH FAR 91.207(D) (DUE 5/24).

STEPHEN STEWART - A&P 2129169

N. C.
N C

Time in	Passengers		
Hrs.	Min.	Carried	
	-	100	
•		Time in Air Hrs. Min.	

#### NATURE OF FLIGHT



9519 Airport Drive, Hanger 19 Visalia, CA 93277

## **Airframe**

DATE: 04/24/23

**MODEL: PA-18-150** 

**ACTT: 3455.0** 

**TACH: 3455.0** 

**REG: N4230Z** 

S/N: 18-8456

ANNUAL INSPECTION COMPLETED THIS DATE. ALL APPLICABLE AD'S CHECKED AND CW OR N/A AS LISTED IN AD LOG. I CERTIFY THAT THIS AIRFRAME WAS INSPECTED IN ACCORDANCE WITH <u>ANNUAL</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

APPROVED FOR RETURN TO SERVICE.

STEPHEN STEWART - IA 2129169

PERTINENT DETAILS ON FILE: W.O. 423042423

Total Forward	7.		 	 4 Destablished	CONTROL OF THE	1.4
Place of Last	Airplane O	verhaul	1			
						No. of No.

NOTICE: -Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.



9540 W. Airport Drive Visalia, CA 93277

#### **Airframe**

DATE: 01/16/2025 MC

MODEL: PA-18-150

ACTT: 3457.64

TACH: 3457.64

**REG: N4230Z** 

S/N: 18-8456

- 1 AD 2024-21-02 N/A BY DATE OF AFFECTED PARTS NOT INSTALLED.
- 2 C/W AD 68-05-01 R1 BY INSPECTION OF EXHAUST. NO DEFECTS NOTED AT THIS TIME.
- 3 INSTALL NEW AIRCRAFT BATTERY P/N: G-35, S/N: G03235480. SERVICED WITH 3 QUARTS OF ACID.
- 4 INSTALL NEW ELT BATTERY P/N: BP-1010.
- 5 INSTALL NEW TAIL TIRE P/N: 06-01245 AND TUBE P/N: 06-00760.
- 6 RESEALED PRIMER PLUNGER.
- 7 INSPECTED ELT IN ACCORDANCE WITH FAR 91.207(D) (BATTERY EXPIRES FEBRUARY 2027).

PERTINENT DETAILS ON FILE: W.O. 423011625

RAPHAEL LOPEZ - IA/AP 2709706



9540 W. Airport Drive Visalia, CA 93277

# <u> Airframe</u>

DATE: 01/16/2025 MODEL: PA-18-150

ACTT: 3457.64

TACH: 3457.64

**REG: N4230Z** 

S/N: 18-8456

ANNUAL INSPECTION COMPLETED THIS DATE. ALL APPLICABLE AD'S CHECKED AND C/W OR N/A AS LISTED IN AD LOG. I CERTIFY THAT THIS AIRFRAME WAS INSPECTED IN ACCORDANCE WITH <u>ANNUAL</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

APPROVED FOR RETURN TO SERVICE.

PERTINENT DETAILS ON FILE: W.O. 423011625

RAPHAEL LOPEZ - IA/AP 2709706

					menometaloreuses menometaloreuses	
	V -			Lynn.	CARAMORAN W	
Total Forwa	ard					
Place	of Last A	lirnler	10 Over	chaul	As the same of the	

Place of Last Airplane Overhaul

Date of Last Overhaul.

NOTICE: -- Making false entries in this book is a violation of the Civil Aeronautics Act of 1938, punishable by Civil Penalty.